


10.1302/2633-1462.51.BJO-2023-0130.R1



**Fig a.** Illustrative example of a case in which the screws were blocked by the opposite screws which originated from the medial plate.