■ HIP

Adverse reaction to metal debris following hip resurfacing

THE INFLUENCE OF COMPONENT TYPE, ORIENTATION AND VOLUMETRIC WEAR

D. J. Langton,
T. J. Joyce,
S. S. Jameson,
J. Lord,
M. Van Orsouw,
J. P. Holland,
A. V. F. Nargol,
K. A. De Smet

From Newcastle University and University Hospital of North Tees, Newcastle-upon-Tyne, United Kingdom

■ D. J. Langton, MBBS, MRCS, Orthopaedic trainee
■ S. S. Jameson, MBBS, MRCS, Orthopaedic trainee
Northern Deanery, Goldcrest Way, Newcastle-upon-Tyne NE15 8NY, UK.

■ T. J. Joyce, PhD, Reader in Biotribology
■ J. Lord, PhD Student
Newcastle University, Claremont Road, Newcastle-upon-Tyne NE1 7RU, UK.

■ M. Van Orsouw, MD, Senior House Officer
■ K. A. De Smet, MD, Consultant Orthopaedic Surgeon
ANCA Medical Centre, Krijgslaan 181, 9000 Ghent, Belgium.

■ J. P. Holland, FRCS (Tr & Orth), Consultant Orthopaedic Surgeon
Freeman Hospital, Freeman Road, High Heaton, Newcastle-upon-Tyne NE7 7DN, UK.

■ A. V. F. Nargol, FRCS (Tr & Orth), Consultant Orthopaedic Surgeon
University Hospital of North Tees, Hardwick Road, Stockton-on-Tees TS19 8PE, UK.

Correspondence should be sent to Mr D. J. Langton; e-mail: djlangton22@doctors.org.uk

©2011 British Editorial Society of Bone and Joint Surgery
doi:10.1302/0301-620X.93B2.25099 \$2.00

J Bone Joint Surg [Br]
2011;93-B:164-71.

Received 12 May 2010;
Accepted after revision 14 October 2010

We sought to establish the incidence of joint failure secondary to adverse reaction to metal debris (ARMD) following metal-on-metal hip resurfacing in a large, three surgeon, multicentre study involving 4226 hips with a follow-up of 10 to 142 months. Three implants were studied: the Articular Surface Replacement; the Birmingham Hip Resurfacing; and the Conserve Plus. Retrieved implants underwent analysis using a co-ordinate measuring machine to determine volumetric wear. There were 58 failures associated with ARMD. The median chromium and cobalt concentrations in the failed group were significantly higher than in the control group ($p < 0.001$). Survival analysis showed a failure rate in the patients with Articular Surface Replacement of 9.8% at five years, compared with $< 1\%$ at five years for the Conserve Plus and 1.5% at ten years for the Birmingham Hip Resurfacing. Two ARMD patients had relatively low wear of the retrieved components. Increased wear from the metal-on-metal bearing surface was associated with an increased rate of failure secondary to ARMD. However, the extent of tissue destruction at revision surgery did not appear to be dose-related to the volumetric wear.

Metal-on-metal (MoM) hip resurfacing devices were re-introduced following a number of design changes.^{1,2} The encouraging early results of the Birmingham Hip Resurfacing (BHR; Smith and Nephew, Warwick, United Kingdom) designers' series³ led to a rapid increase in the number of surgeons carrying out the procedure. A number of manufacturers subsequently developed their own implants, resulting in the large number of resurfacing systems in regular use in Europe and the United States.⁴ Each commercially available device has a different combination of modifications of the original designs.⁵ The central design features which are thought to influence wear are: the use of 'as cast' *versus* forged material; varying heat treatments of the femoral and acetabular components; the difference in diameter between mated components (the diametral clearance); the arc of acetabular cover, and the angle of function of the femoral component.⁵⁻¹⁰

With the technology currently available, the MoM bearing surface remains integral to the design of hip resurfacing. The main drawback of a metal articulation is the production of metal debris due to the combined effect of mechanical and corrosive wear. In fact, the popularity of the procedure has waned in the last two years following a number of reports

of adverse reactions in the peri-prosthetic tissues of resurfaced hips.¹¹⁻¹⁵

We have previously highlighted the disparity in blood chromium (Cr) and cobalt (Co) levels between patients receiving different hip resurfacings¹⁶ and have identified a relationship between increased wear of the articular surface and the incidence of soft-tissue lesions.¹⁷ The aim of this study was to involve other centres and thereby increase the number of hip resurfacing procedures available for analysis in order to gain more understanding of the incidence of adverse reactions to metal debris (ARMD) in three commonly used hip resurfacing arthroplasty designs, further investigate the clinical effects of increased wear debris from MoM hip resurfacings, and determine whether the extent of tissue destruction in ARMD is related to volumetric wear from the bearing surfaces. ARMD is an umbrella term.¹⁷ It is used to describe joint failure secondary to surface wear of the bearing surface or corrosion debris, in the absence of any other obvious explanation. It encompasses metallosis, pseudotumour and aseptic lymphocyte-dominated vasculitis associated lesion (ALVAL).¹⁸

Patients and Methods

Three implant designs were used in the study: A: the Articular Surface Replacement (ASR;

Table I. Details of the three devices

	Component*		
	ASR	BHR	C+
Subtended articular surface angle (°)	144 to 160 [†]	158 to 166 [†]	162 to 165
Mean radial clearance (µm)	50	100	80
Impingement-free range of movement(°) [‡]	37.0 to 28.0	40.2 to 30.0	38.5 to 32
Wall thickness at rim (mm)	3.1	3.6/4.6	3.8
Manufacturing method of head	As cast	As cast	HIP/SA [§]
Manufacturing method and treatment of component	HIP/SA	As cast	HIP/SA
Surface roughness (µm)	0.025	0.029	0.020
Deviation of roundness head (µm)	3.4	0.9	3.2
Deviation of roundness component (µm)	3.8	0.9	1.8
Carbon content [¶]	High	High	High

* ASR, Articular Surface Replacement; BHR, Birmingham Hip Resurfacing; C+, Conserve Plus

[†] subtended articular surface angles increase with increasing component diameter

[‡] this refers to the maximum arc of movement in a single plane prior to impingement of the femoral neck on the rim of the acetabular component, assuming that the neck is flush to the base of the femoral component and that impingement will take place on the articular rim of the BHR and the C+ components and on the outer rim of the ASR component. The range of motion decreases with increasing component size for all devices

[§] HIP/SA, cast process and heat treatment by hot isostatic pressure/surface annealed

[¶] High carbon content is defined as $\geq 0.2\%$

Source: manufacturers' details and independent testing⁵

Table II. Patient demographics, joint orientations and metal ion concentrations (centre 1). All values are mean values (range) unless marked with * in which case they are median values

	Design A	Design B
Demographics		
Number of hips	430	180
Age (yrs)	56 (28 to 77)	51 (32 to 67)
% Female	44	43
Follow-up (mths)	37 (10 to 67)	65 (59 to 87)
Femoral size (mm)	48.6 (39 to 59)	47.6 (38 to 58)
Inclination angle (°)	48.5 (31 to 70)	48.3 (32 to 70)
Anteversion angle (°)	20.4 (3 to 39)	19.9 (-5 to 39)
Outcome scores		
Harris Hip Score	93 (35 to 100)	97 (51 to 100)
Total ion results		
	156	95
Serum metal ion levels		
Cr (µg/L)*	4.00 (0.6 to 115)	4.42 (1.8 to 77)
Co (µg/L)*	2.60 (0.4 to 228)	1.56 (0.7 to 190)
Whole blood metal ion levels		
Cr (µg/L)*	3.89 (1.5 to 69.8)	3.92 (2.37 to 40)
Co (µg/L)*	2.39 (0.4 to 271)	1.44 (0.63 to 147)
Adverse reaction to metal debris failure at a minimum of ten months (%)	27 (6.3)	1 (0.56)

DePuy, Leeds, United Kingdom); B: BHR; C: Conserve Plus (C+; Wright Medical, Memphis, Tennessee). The important differences between the three devices can be seen in Table I.

All the patients of three experienced hip resurfacing surgeons (AVFN, KDS, JPH) who received a design A, B or C resurfacing prosthesis between January 1998 and January 2009 were involved in this study. A total of 4226 hips in 3888 patients were studied. Details of the patients are

shown in Tables II, III and IV. Surgeon 1 (AVFN) is based in the United Kingdom (University Hospital of North Tees, Stockton, United Kingdom). Between 2002 and 2004 he used design B for all resurfacing procedures. From 2004 he used design A exclusively. This cohort of patients has been described previously.^{17,19} From 2007, patients at this centre have undergone routine whole blood and serum metal ion testing.²⁰ Surgeon 2 (KDS) is based in Belgium (ANCA

Table III. Patient demographics, joint orientations and metal ion concentrations (centre 2). All values are mean values (range) unless marked with * in which case they are median values

	Design A	Design B	Design C
Demographics			
Number of hips	59	1922	961
Age (yrs)	54 (27 to 69)	52 (20 to 79)	55 (20 to 80)
% Female	39	39	41
Follow-up (mths)	31 (11 to 58)	68 (10 to 142)	34 (10 to 82)
UCLA [†] score	6.2 (5 to 9)	7.4 (3 to 10)	7.0 (4 to 10)
Femoral size (mm)	50.7 (45 to 59)	49.8 (38 to 58)	48.4 (38 to 62)
Inclination angle (°)	49.8 (32 to 60)	51.8 (32 to 70)	49.0 (31 to 65)
Anteversion angle (°)	20.8 (0 to 42)	21.8 (0 to 41)	22.3 (3 to 44)
Outcome scores			
Harris Hip Score	97 (27 to 100)	98 (27 to 100)	98 (29 to 100)
Total ion results	26	368	144
Serum metal ion levels			
Cr (µg/L)*	1.6 (0.6 to 184)	2.6 (0.8 to 93)	1.8 (0.3 to 40)
Co (µg/L)*	1.9 (0.6 to 235)	1.9 (0.5 to 119)	1.4 (0.4 to 55)
Adverse reaction to metal debris failure at a minimum of ten months (%)	2 (3.4)	23 (1.5)	4 (0.42)

Table IV. Patient demographics, and joint orientations (centre 3). Values are mean (range)

	Design B
Demographics	
Number of hips	674
Age (yrs)	49 (22 to 70)
% Female	32
Follow-up (mths)	65 (10 to 130)
Femoral size (mm)	51.0 (38 to 62)
Inclination angle (°)	44.9 (30 to 64)
Anteversion angle (°)	14.8 (0 to 28)
Outcome scores	
Harris Hip Score	97
Adverse reaction to metal debris (%)	3 (0.45)

Clinic, Ghent, Belgium). He initially used design B but has subsequently also used designs A and C. Routine serum metal ions analysis is undertaken post-operatively. The early results of the patients receiving design B at this centre have been published previously.²¹ Surgeon 3 (JPH) is based in the United Kingdom (Freeman Hospital, Newcastle-upon-Tyne, United Kingdom) and uses design B exclusively. All surgeons used the posterior surgical approach.

At all centres, outcomes were assessed at six months, at one year and annually thereafter using the Harris hip score²² and the UCLA activity score. Any patient whose hip was revised or was listed for revision secondary to ARMD at the time of writing was recorded. At centres 1 and 2, standing radiographs were obtained at the time of blood sampling and analysed using EBRA software (University of Innsbruck, Innsbruck, Austria) to measure the inclination

and anteversion of the acetabular component.^{23,24} This was carried out by one of the authors (DJL). At centre 3, the first 100 well-centred digitised standing radiographs were analysed in order to provide an assessment of the orientation of the acetabular component, whose position was allocated a 'zone' as shown in Figure 1. Zone 1 corresponds to a safe zone derived from our previous work based upon an analysis of metal ion results and explants.²⁵

The diagnosis of ARMD was made by the consultant in charge and was based on clinical presentation, findings at revision and the histological appearance of capsular tissue taken at revision surgery. The appearance of the peri-prosthetic tissues at revision was graded as follows: 0, no soft-tissue necrosis; 1, small localised areas of tissue necrosis; 2, widespread tissue necrosis, stability of the implant not obviously compromised and 3, widespread tissue necrosis with compromised stability of the implant.

Serum metal ion analysis. Blood samples for Cr and Co analysis were taken more than 12 months post-operatively to avoid the confounding effects of the running-in period.²⁶ The methods of sampling and ion analysis at both centres have been described previously.^{20,27}

Histopathological examination of tissues from revision procedures at centre 1. The processing of tissue specimens has also been described previously.¹⁷ In our experience, the vast majority of tissues retrieved from ARMD patients exhibit two dominant, and often co-existent, cellular responses: histiocytic and lymphocytic. For the purpose of this paper, tissues were described as having a dominant 'histiocytic' response if there was a band of histiocytes > 1.5 mm in width or a dominant lymphocytic (ALVAL) response if there were multiple perivascular lymphocytic cuffs > 1.5 mm in size. Metal particulate load in the tissues was graded using a scale

Fig. 1

Box plot showing all measured acetabular component orientations in the study (black plots) with adverse reaction to metal debris (ARMD) failure components represented by $\blacklozenge$. Each surgeon in the study achieved zone 1 placement in < 30% of cases. This is the reason for quoting figures for an 'expanding safe zone' (zones 2 and 3 incorporate each other) in order to represent zones more representative of clinical practice. Design B patients with femoral sizes ≤ 42 mm placed outside of safe zone 1 have a 3.4% risk of ARMD, reinforcing the idea that failure is strongly related to size as well as design. Zone 1: 40° to 50° inclination and 10° to 20° anteversion; zone 2: 35° to 55° and 5° to 25° ; zone 3: 30° to 60° and 0° to 30° ; zone 4: $> 60^\circ$ and $< 30^\circ$; zone 5: $< 60^\circ$ and $> 30^\circ$; zone 6: $> 60^\circ$ and $> 30^\circ$.

similar to Mirra's classification²⁸ in order to allow correlation with the rate of volumetric wear. We used a more reproducible grading system derived from the assessment of tissue iron in liver biopsies. It is based upon the ease of identification of particles and the magnification power used to identify them: 0, granules absent or barely discernable at $\times 400$; 1, easily confirmed at $\times 400$, barely discernable at $\times 250$; 2, discrete granules resolved at $\times 100$; 3, discrete granules resolved at $\times 25$; 4, masses visible to the naked eye.

The average diameter of the lymphocytic cuff, the width of the histiocytic band and the integrity of the surface membrane were recorded for each patient and correlated to the rate of volumetric wear.¹⁷

Explant analysis. The wear of all available femoral and acetabular explants from centres 1 and 3 was measured by a co-ordinate measuring machine using a scanning head (Legex 322; Mitutoyo, Halifax, United Kingdom) with a spatial resolution of $< 1 \mu\text{m}$ in the area of measurement. Volumetric wear was calculated using a validated method.²⁹ Volumetric wear rates were correlated with serum metal ion results using Spearman rank univariate analysis.

Survival analysis. A Cox proportional hazards model was constructed using surgeon and implant design as qualitative variables and bearing diameter as a quantitative variable. Given the numbers involved in the study, a p-value of < 0.01 was considered to be statistically significant.

Table V. Results of Cox proportional hazards model

	Hazard ratio	Significance
Design		
A	42.887	$p < 0.001$
B	4.354	$p = 0.048$
C	1	NA*
Surgeon		
1	1.860	$p = 0.314$
2	2.377	$p = 0.232$
3	1	NA
Bearing diameter	0.907	$p = 0.002$

* NA, not available

Results

At the time of writing, there were 60 failures related to ARMD. The incidence of ARMD by centre was as follows.

Centre 1. There was a clear difference in the failure rates between the design A and B patient groups. At a mean follow-up of 65 months (59 to 87), one design B patient had been revised. This was in contrast to the design A group, in which 24 hips had been revised and three more were awaiting revision, amounting to a failure rate of 6.3% at a mean follow-up of 37 months (10 to 67).

Centre 2. Two patients with unilateral design A resurfacings had undergone revision, amounting to a rate of revision of 3.4% at a mean follow-up of 31 months (11 to 58). The failure rate secondary to ARMD was 1.2% (23 cases) in the design B group, at a mean follow-up of 68 months (10 to 142) and 0.42% (two cases) in the design C group at a mean follow-up of 37 months (10 to 82).

Centre 3. Only design B was used here, and three patients had been revised. This amounted to a failure rate of 0.45% at a mean follow-up of 65 months (10 to 130).

Survival analysis. Cox proportional hazards model showed that patients receiving design A implants were at a significantly greater risk of ARMD failure than patients with designs B and C. Smaller implants were at greater risk of early failure but the surgeon performing the procedure did not significantly affect survival (Table V).

The most common presenting symptom was pain, located predominantly in the groin and occasionally radiating to the greater trochanter and down the thigh, and frequently associated with clicking and clunking sensations. One hip was asymptomatic but as the patient had experienced a severe ARMD with an ASR (DePuy) total hip replacement on one side she asked for the contralateral ASR to be revised. At revision, there were variable degrees and combinations of soft-tissue necrosis, joint effusions in 30, macroscopic metallosis in 18, component loosening in eight and masses in 17. In some cases the effusion was massive (> 200 ml) and had extended through the abductor

Table VI. Comparison of size, component orientations and metal ion levels between the asymptomatic and adverse reaction to metal debris (ARMD) cohorts. Median (range) values are given with Mann-Whitney U test for non-parametric data used to establish significance of results

	ARMD	Asymptomatic	p-value
Femoral size	46.00 (38 to 57)	50.00 (38 to 62)	< 0.001
Component inclination (°)	50.95 (31 to 70)	49.05 (23 to 78)	0.110
Component anteversion (°)	25.00 (-9 to 44)	16.28 (-9 to 42)	< 0.001
Serum Cr (µg/L)	26.05 (1.6 to 146)	2.9 (0.5 to 110)	< 0.001
Serum Cr (µg/L)	39.45 (1.1 to 228)	1.9 (0.3 to 155)	< 0.001

Fig. 2

Graph showing failure rates for each device, with patients split into groups by femoral component size. All patients in the study are included, although the design group A patients with femoral size of 39 mm are removed for graphical representation. There were two patients in this group, with one failure, amounting to a 50% failure rate. ▲, design A patients; ■, design B patients; △, design C patients.

musculature. The asymptomatic patient described above had severe soft-tissue destruction. Four patients presented with painless swellings in the lateral thigh and groin (two design B, two design A), one associated with femoral nerve symptoms. Revision surgery in these cases revealed psoas bursae containing caseous material. At centre 1, five male patients with design A implants were found to have increased levels of Cr and Co on routine screening. As they were asymptomatic they were simply observed. All five patients became symptomatic. Fractures of the femoral neck in association with gross macroscopic metallosis were found at revision. A psoas mass was also identified in one of these cases. Soft-tissue destruction was not extensive in these cases. Patients who were found to have a large effusion at revision surgery were revised significantly earlier than those found to have masses at revision

Fig. 3

Box plot showing metal ion data for all implant designs. The inferior, middle and superior horizontal lines of the boxes represent the first quartile, median and third quartile. The ends of the whiskers correspond to the limits of the data, beyond which values are considered anomalous. The mean is displayed with a +, outliers with a °, extreme outliers with a * and upper and upper and lower values with ●.

(median time to revision (effusion) 21 months *versus* 52 months (masses), $p < 0.001$).

Table VI shows the significant differences in bearing size, acetabular component orientation and metal ion levels between the asymptomatic and ARMD cohorts. There was a clear trend towards increased risk of failure with decreasing size of femoral component in the three centres (Fig. 2). Figure 1 shows the relationship between the angle of inclination and anteversion of the acetabular component and failure. In two ARMD acetabular components we found they were in the safe zone for metal ion reduction ($45^\circ \pm 5^\circ$ inclination and $15^\circ \pm 5^\circ$ for anteversion).²⁵ An overview of the metal ion results for each implant

group can be seen in Figure 3. Median levels of Cr and Co in ARMD patients ($n = 37$ with pre-revision ion levels) were significantly higher than in the asymptomatic cohort, with the median Co concentration $\times 20$ greater in the failed group. The two patients described above, with acetabular components in the safe zone, did have ion levels comparable with the asymptomatic cohort (Co levels of $2.1 \mu\text{g/l}$ and $1.9 \mu\text{g/l}$). Histology of the tissue specimens showed no macroscopic metallosis but a dominant ALVAL reaction. Both of these patients had grade 2 soft-tissue destruction at revision surgery.

Total rates of volumetric wear correlated well with serum Cr ($r = 0.847$, $p < 0.001$) and Co levels ($r = 0.732$, $p < 0.001$) and with particulate tissue load ($r = 0.60$, $p < 0.001$), but not with perivascular lymphocytic cuff thickness, histiocyte band width, surface membrane necrosis or macroscopic tissue necrosis at revision surgery. A relationship was identified between lymphocytic cuff diameter and surface membrane necrosis ($r = 0.55$, $p = 0.011$).

Discussion

This paper represents the largest collection of clinical and biochemical results from hip resurfacing patients in the current literature. We believe that the three-centre nature of the study, the experience of the surgeons involved and the use of three resurfacing designs provides a fair representation of the performance of modern hip resurfacing in the wider orthopaedic community.

Currently there is increasing concern over the potential adverse effects of metal debris. It remains to be shown whether these adverse reactions are dose-dependent and whether they are mediated primarily by an immune response to, or a direct toxic effect of the metal debris. Reported rates of ALVAL,²¹ pseudotumours⁹ and metallosis¹² vary throughout the literature. There appears to be no consensus as to the boundaries between the described conditions. Liu et al⁹ define pseudotumour as “a soft-tissue mass associated with the implant which is neither malignant nor infective in nature”. It is not clear whether this term includes joint effusion. ALVAL is a histological diagnosis²¹ which has also been used to describe the clinical appearance of tissue necrosis and abnormal joint fluid at revision surgery.³⁰ Metallosis is defined as aseptic fibrosis, local necrosis, or loosening of a device secondary to metallic corrosion and release of wear debris.^{31,32} At centre 1, metallic debris was identified, at least on a microscopic scale, in every tissue sample removed from ARMD joints. This is consistent with previous reports.³³ In a number of tissue specimens, marked lymphocytic infiltration (ALVAL) was observed, co-existent with abundant particulate-laden histiocytes. The pathogenesis of these cellular processes is beyond the scope of this paper, hence our reason to use the umbrella term ARMD in order to determine the overall incidence of unsatisfactory clinical outcomes attributed to wear from MoM bearing surfaces.

Fig. 4

Kaplan Meier survival chart for the three implants (adverse reaction to metal debris failures only). Design A in red (87.2% survival at five years), design B in blue (99.1% at five years), and design C (99.6% survival at five years) in black. Dotted lines represent 95% confidence intervals.

In a smaller, single surgeon, single-site study, we previously highlighted clear differences in the release of metal ions between two resurfacing devices (designs A and B in the present study).¹⁶ De Smet et al²⁷ demonstrated that serum metal ion concentrations correlate well with wear of retrieved femoral components. By using Cr and Co analysis as a surrogate indicator of wear, we therefore concluded that increased wear was associated with an increased probability of early failure. These results have been substantiated here. In this series, design A has the highest rate of failure secondary to ARMD (Fig. 4). It is also the most vulnerable to the effects of variation in acetabular component position in terms of ion generation. Design B is associated with a smaller range of Cr and Co values than design A and this is reflected in the lower failure rates secondary to ARMD. Patients receiving design C have the lowest serum ion levels and also the lowest failure rates secondary to ARMD. An obvious confounding factor here, however, is that the design C patients have a shorter mean follow-up than those with design B resurfacings. The Cox proportional hazards model should account for this factor in our analysis; however, we interpret these results with caution. The proportional hazards model we used will not account for unknown specific design features which may have an unexpected effect once a certain period of time has elapsed.

There is overwhelming evidence to show that surgeons cannot consistently position the acetabular components precisely. Without exception, studies show wide variations in the angles of inclination of the acetabular component and, to an even greater extent, its anteversion (Fig. 5).³⁴ Surgeons must accept that some variables may be beyond their control, for example changes in pelvic tilt³⁵ during

Fig. 5

Box plot showing acetabular component orientations of the surgeons in this study. The inferior, middle and superior horizontal lines of the boxes represent the first quartile, median and third quartiles. The ends of the whiskers correspond to the limits of the data, beyond which values are considered anomalous. The mean is displayed by +.

pre-operative positioning, intra-operative pelvic rotation³⁶ and patient size. Consequently they should choose implants which are compatible with the inevitable variability of acetabular component orientation.

While the three resurfacing systems have differences of design including varying clearances, heat treatment or no heat treatment of both the femoral and acetabular components, we believe that the design feature most likely to explain the disparity in performance is the arc of acetabular cover. The acetabular component of design C has a smaller arc of cover than the other devices (Table I). Despite this decreased cover, the range of motion prior to impingement is not compromised firstly, due to the recessed nature of the articular surface and also due to the smaller functional angle of the femoral component relative to the other two designs. These features increase the vulnerability of the device to the two mechanisms which appear to be critical in the acceleration of wear rates: edge-loading and microseparation/subluxation.³⁷⁻³⁹ The smaller arc of the cover, i.e. the more shallow the acetabular component, the greater is the tendency to rim-loading at equivalent angles of inclination and anteversion, when matched for size.

There are likely to be important factors other than those described above. Two design A devices were found to have radial clearances of < 60 µm, meaning that any distortion of the acetabular components *in vivo*⁴⁰ may be very detrimental. This is currently under investigation.

Fig. 6

Line graph showing acetabular component placement zones as described in Figure 2. This chart shows the incidence of adverse reaction to metal debris (ARMD) for each design with relation to acetabular component orientation.

The relationship between the amount of wear debris and the extent of tissue destruction is not straightforward. Using serum ion levels as a surrogate measure, our results suggest that, when exposed to low levels of wear, most patients with a resurfaced hip do extremely well.⁴¹ Whether or not there is a causal relationship, patients exposed to more debris are more likely to have complications. In this series, the patients with extremely high levels of metal ions/wear from the bearing surfaces did not, however, present exclusively with worsening pain, but with other symptoms including delayed fracture of the femoral neck and/or masses. At revision surgery, macroscopic metallosis was the dominant feature. This was in contrast to the striking appearance of joint fluid and tissue necrosis, which was seen in patients with moderately increased wear/metal ion levels. Neither volumetric wear rates nor joint/serum ion concentrations correlated with microscopic necrosis or the extent of tissue destruction observed at revision surgery. The relationship between the thickness of perivascular lymphocytic cuffs and surface layer necrosis suggests that tissue destruction is not a result of toxic concentrations of metal debris, but is more likely to be the result of an immune response provoked by the debris.⁴² Patients found to have pseudotumours were revised at a significantly longer period from primary surgery than those with no masses. We speculate that pseudotumours are part of the same pathological spectrum of disease which causes joint effusions and tissue death, but is a more advanced stage of the disease process. Metallic debris produced by different devices may have different sizes and shapes⁴³ and wear particles produced by design A could conceivably have greater immunogenicity.

The central message, however, is that in the short- to mid-term at least, the vast majority of patients with MoM resurfaced hips will not experience severe soft-tissue reactions when exposed to the levels of wear associated with well-functioning bearing surfaces.

We conclude that increased wear from MoM hip resurfacing is associated with an increased probability of adverse clinical outcomes. These adverse outcomes include severe destruction of soft tissues and bony necrosis. It is likely that a provoked immune response is primarily responsible for the observed soft-tissue destruction, but in most patients high levels of wear are needed to instigate this negative cascade of events. We estimate that < 1% of patients develop reactions to normally wearing-bearing surfaces.

Supplementary material

A table showing the explant analysis and dominant cellular response of failed devices from centres 1 and 3 is available with the electronic version of this article on our website at www.jbjs.org.uk

Listen live

Listen to the abstract of this article at www.jbjs.org.uk/interactive/audio

No benefits in any form have been received or will be received from a commercial party related directly or indirectly to the subject of this article.

References

- Shimmin A, Beaulé PE, Campbell P. Metal-on-metal hip resurfacing arthroplasty. *J Bone Joint Surg [Am]* 2008;90-A:637-54.
- McMinn D, Treacy R, Lin K, Pynsent P. Metal on metal surface replacement of the hip: experience of the McMinn prosthesis. *Clin Orthop* 1996;329(Suppl):89-98.
- Treacy RB, McBryde CW, Pynsent PB. Birmingham hip resurfacing arthroplasty: a minimum follow-up of five years. *J Bone Joint Surg [Br]* 2005;87-B:167-70.
- No authors listed. 6th Annual Report of the National Joint Registry for England and Wales. <http://www.njrcentre.org.uk> (date last accessed 22 October 2010).
- Heisel C, Kleinhans JA, Menge M, Kretzer JP. Ten different hip resurfacing systems: biomechanical analysis of design and material properties. *Int Orthop* 2009;33:939-43.
- Bowsher JG, Nevelos J, Williams PA, Shelton JC. 'Severe' wear challenge to 'as-cast' and 'double heat-treated' large-diameter metal-on-metal hip bearings. *Proc Inst Mech Eng H* 2006;220:135-43.
- Smith SL, Dowson D, Goldsmith AA. The effect of femoral head diameter upon lubrication and wear of metal-on-metal total hip replacements. *Proc Inst Mech Eng H* 2001;215:161-70.
- Rieker CB, Schön R, Konrad R, et al. Influence of the clearance on in-vitro tribology of large diameter metal-on-metal articulations pertaining to resurfacing hip implants. *Orthop Clin North Am* 2005;36:135-42.
- Liu F, Jin ZM, Hirt F, et al. Effect of wear of bearing surfaces on elastohydrodynamic lubrication of metal-on-metal hip implants. *Proc Inst Mech Eng H* 2005;219:319-28.
- Daniel J, Ziaee H, Kamali A, et al. Ten-year results of a double-heat-treated metal-on-metal hip resurfacing. *J Bone Joint Surg [Br]* 2010;92-B:20-7.
- Pandit H, Glyn-Jones S, McLardy-Smith P, et al. Pseudotumours associated with metal-on-metal hip resurfacings. *J Bone Joint Surg [Br]* 2008;90-B:847-51.
- Ollivere B, Darrah C, Barker T, Nolan J, Porteous MJ. Early clinical failure of the Birmingham metal-on-metal hip resurfacing is associated with metallosis and soft-tissue necrosis. *J Bone Joint Surg [Br]* 2009;91-B:1025-30.
- Counsell A, Heasley R, Arumilli B, Paul A. A groin mass caused by metal particle debris after hip resurfacing. *Acta Orthop Belg* 2008;74:870-4.
- Hart AJ, Sabah S, Henckel J, et al. The painful metal-on-metal hip resurfacing. *J Bone Joint Surg [Br]* 2009;91-B:738-44.
- Kwon YM, Glyn-Jones S, Simpson DJ, et al. Analysis of wear of retrieved metal-on-metal hip resurfacing implants revised due to pseudo-tumours. *J Bone Joint Surg [Br]* 2010;92-B:356-61.
- Langton DJ, Sprowson AP, Joyce TJ, et al. Blood metal ion concentrations after hip resurfacing arthroplasty: a comparative study of articular surface replacement and Birmingham Hip Resurfacing arthroplasties. *J Bone Joint Surg [Br]* 2009;91-B:1287-95.
- Langton DJ, Jameson SS, Joyce TJ, et al. Early failure of metal-on-metal bearings in hip resurfacing and large-diameter total hip replacement: a consequence of excess wear. *J Bone Joint Surg [Br]* 2010;92-B:38-46.
- Willert HG, Buchhorn GH, Fayyazi A, et al. Metal-on-metal bearings and hypersensitivity in patients with artificial hip joints: a clinical and histomorphological study. *J Bone Joint Surg [Am]* 2005;87-A:28-36.
- Jameson SS, Langton DJ, Natsu S, Nargol TV. The influence of age and sex on early clinical results after hip resurfacing: an independent centre analysis. *J Arthroplasty* 2008;23(Suppl 1):50-5.
- Langton DJ, Jameson SS, Joyce TJ, Webb J, Nargol AV. The effect of component size and orientation on the concentration of metal ions after resurfacing arthroplasty of the hip. *J Bone Joint Surg [Br]* 2008;90-B:1143-51.
- De Smet KA. Belgium experience with metal-on-metal surface arthroplasty. *Orthop Clin North Am* 2005;36:203-13.
- Harris WH. Traumatic arthritis of the hip after dislocation and acetabular fractures: treatment by mold arthroplasty: an end-result study using a new method of result evaluation. *J Bone Joint Surg [Am]* 1969;51-A:737-55.
- Langton DJ, Sprowson AP, Mahadeva D, et al. Cup anteversion hip resurfacing: validation of EBRA and the presentation of a simple clinical grading system. *J Arthroplasty* 2010;25:607-13.
- Malviya A, Lingard EA, Malik A, Bowman R, Holland JP. Hip flexion after Birmingham Hip Resurfacing: role of cup anteversion, anterior femoral head-neck offset and head-neck ratio. *J Arthroplasty* 2010;25:387-91.
- Langton DJ, Joyce TJ, Jameson SS, De Smet K, Nargol AV. Serum metal ion concentrations post hip resurfacing arthroplasty: cup design and position is critical. American Academy of Orthopaedic Surgeons Annual Meeting, New Orleans, 2010.
- Heisel C, Streich N, Krachler M, Jakubowitz E, Kretzer JP. Characterization of the running-in period in total hip resurfacing arthroplasty: an in vivo and in vitro metal ion analysis. *J Bone Joint Surg [Am]* 2008;90-A(Suppl 3):125-34.
- De Smet K, De Haan R, Calistri A, et al. Metal ion measurement as a diagnostic tool to identify problems with metal-on-metal hip resurfacing. *J Bone Joint Surg [Am]* 2008;90-A(Suppl 4):202-8.
- Doorn PF, Mirra JM, Campbell PA, Amstutz HA. Tissue reaction to metal on metal total hip prosthesis. *Clin Orthop* 1996;329:5187-207.
- Lord J, Joyce T, Langton D, Nargol A. The wear of explanted Resurfacing Hip Prostheses. *J Biomech* 2010;43:546.
- Karva AR, Board TN, Mohan S, Porter ML. Revision of failed hip resurfacing due to metal hypersensitivity (ALVAL). *J Bone Joint Surg [Br]* 2009;91-B(Suppl 3):406.
- Doorn PF, Mirra JM, Campbell PA, Amstutz HC. Tissue reaction to metal on metal total hip prostheses. *Clin Orthop* 1996;329(Suppl):187-205.
- De Haan R, Campbell PA, Su EP, De Smet KA. Revision of metal-on-metal resurfacing arthroplasty of the hip: the influence of malpositioning of the components. *J Bone Joint Surg [Br]* 2008;90-B:1158-63.
- Witzleb WC, Hanisch U, Kolar N, Krummenauer F, Guenther KP. Neo-capsule tissue reactions in metal-on-metal hip arthroplasty. *Acta Orthop* 2007;78:211-20.
- Hassan DM, Johnston GH, Dust WN, Watson G, Dolovich AT. Accuracy of intraoperative assessment of acetabular prosthesis placement. *J Arthroplasty* 1998;13:80-4.
- Babisch JW, Layher F, Amiot LP. The rationale for tilt-adjusted acetabular cup navigation. *J Bone Joint Surg [Am]* 2008;90-A:357-65.
- Asayama I, Akiyoshi Y, Naito M, Ezoe M. Intraoperative pelvic motion in total hip arthroplasty. *J Arthroplasty* 2004;19:992-7.
- Morlock MM, Bishop N, Zustin J, et al. Modes of implant failure after hip resurfacing: morphological and wear analysis of 267 retrieval specimens. *J Bone Joint Surg [Am]* 2008;90-A(Suppl 3):89-95.
- Nevelos J, Ingham E, Doyle C, et al. Microseparation of the centres of alumina-alumina artificial hip joints during simulator testing produces clinically relevant wear rates and patterns. *J Arthroplasty* 2000;15:793-5.
- Leslie IJ, Williams S, Isaac G, Ingham E, Fisher J. High cup angle and microseparation increase the wear of hip surface replacements. *Clin Orthop* 2009;467:2259-65.
- Lin ZM, Meakins S, Morlock MM, et al. Deformation of press-fitted metallic resurfacing cups. Part 1: experimental simulation. *Proc Inst Mech Eng H* 2006;220:299-309.
- Treacy RBC, McBryde CW, Shears E, Pynsent PB. Birmingham hip resurfacing: a minimum follow-up of ten years. *J Bone Joint Surg [Br]* 2011;93-B: in press.
- Caicedo MS, Desai R, McAllister K, et al. Soluble and particulate Co-Cr-Mo alloy implant metals activate the inflammasome danger signaling pathway in human macrophages: a novel mechanism for implant debris reactivity. *J Orthop Res* 2009;27:847-54.
- Williams S, Tipper JL, Ingham E, Stone MH, Fisher J. In vitro analysis of the wear, wear debris and biological activity of surface-engineered coating for use in metal-on-metal total hip replacements. *Proc Inst Mech Eng H* 2003;217:155-63.